	araine unitarial entering		201110700	
	day, 7/9/2007 11:53:30 AM Proce	ess Sheet	SP/1te	31
Customer Job Number Estimate Number P.O. Number This Issue Prsht Rev. First Issue Previous Run Written By Checked & Approv. Comment	: Est Rev:A 04.09.08 New Issue KJ/JLM	Part Number Drawing Number Project Number Drawing Revision Material Due Date	: HEAD REST ASSEMBLY CENTER  : D412724041  : N/A  : N/A  : N/A  : N/A  : N/A  : N/A  : N/A	R  A Um: Each
Additional Product  Job Number:				
		Description :		
Seq. #:	Machine Or Operation:	Description : ENT CONTROL		
1.0	DC DOCUME	:NI CONTROL		
Comm	ent: DOCUMENT CONTROL		111 000 5905	
	If D412-724-041 is a W/O on it's own, Photocopy bluefile and create labels per PPP D412-		Allo CEP 1025 905	
2.0		ING RESOURCE #1		
Commo	ent: PACKAGING RESOURCE #1			
3.0	Pick Packing Kit D3303041 Head Res	st		
5,210.01				
Commo	ent: Qty.: 1.0000 Each(s)/Unit Total: 4.0000 Each Pick: Packing Kit Qty Part Number Description Batch 1 D3303-041 Head Rest 5 27568	ach(s)		1.0
4.0	D3304041 Tube Asse			
Comme	ent: Qty.: 1.0000 Each(s)/Unit Total: 4.0000 Ea Pick: Packing Kit Qty Part Number Description Batch 1 D3304-041 Tube Assembly 32982			
5.0	AN52510R6 Screw  ent: Qty.; 4.0000 Each(s)/Unit Total : 16.0000 Each	ach(s)		
	Pick: Packing Kit  Qty Part Number Description Batch  A ANS25 10R6 Screw MI5 943	/	Sot!	18/07/2

Page

Form: mrocess

Dart Ae	rospace L	td							
W/O:	136		WORK ORDER O	HANGES					
DATE	STEP	PRO	OCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Category:	NC				Date: <u>&lt;</u>	91/00/060
NCR:		1	WORK ORDER NON-CON	FORMANCE					
DATE	STEP	Description of NC	Corrective Action		Sign 8	Verific	cation	Approval	Approval

NCR:			WORK ORDI	ER NON-CONFORMANO	CE (NCR)			
DATE S		Description of NC	Corrective Action Section B			Verification	Annroval	Anneousl
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector

NOTE: Date & initial all entries

Date: Monday, 7/9/2007 11:53:36 AM User: • Kim Johnston **Process Sheet** Drawing Name: HEAD REST ASSEMBLY CENTER Customer: CU-DAR001 Dart Helicopters Services Part Number: D412724041 Job Number: 33403 Job Number: Description: Seq. #: Machine Or Operation: QC4 Comment: INSPECT 100% KITS FOR COMPLETENESS 7.0 Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPP D412-724-041 Location: PPP Rev: FINAL INSPECTION WIO RELEASE 8.0 QC21 80/180/50 Comment: FINAL INSPECTION/W/O RELEASE Jul 07-08.07 Job Completion

Dart Ae	rospace	Ltd								
W/O:	20	-	WC	RK ORDER CHANGI	ES					
DATE	STEP PROCEDURE CHANGE			Е	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No	;	PAR #:	Fault Cateç	jory:					Date:	
NCR:		V	VORK ORDE	R NON-CONFORMA	NCE (	NCR)	)		<u> </u>	
DATE	STEP	Description of NC Section A				Sign & Date		ation on C	Approval Chief Eng	Approval QC Inspector
			55. 25	Chief Eng						

DATE STEP Description of NC Section A	Description of NC		GOTTECTIVE ACTION GECTION B			Approval	Annroval	
	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector		
				it. Vi				

NOTE: Date & initial all entries